

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਤੇ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ

ਦੂਜੀ ਮੰਜਿਲ ਬਲਾਕ-2, ਜਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ ਸੰਗਰੂਰ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰਬਰ. 01672-234114

EMAIL:-sdeprovincialsangrur@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,  
ਹੇਲੀ ਹਾਰਟ ਸੀਨੀਅਰ ਸੈਕੰਡਰੀ ਕੋਨਵੈਂਟ ਸਕੂਲ,  
ਸੰਗਰੂਰ।

ਨੰ: 5

ਮਿਤੀ:- 1-4-2025

ਵਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰ. HHSSCS/2655/2025 ਮਿਤੀ 13.03.2025 ਵੱਲ ਕਾਰਜਕਾਰੀ  
ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਤੇ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ  
ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ  
ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 20,000/- ਜੀ.ਆਰ. ਨੰ. 675556 ਮਿਤੀ 28.03.2025 ਰਾਹੀਂ ਜਮ੍ਹਾਂ  
ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਵੱਲੋਂ ਨਾਲ ਨੱਥੀ ਕੀਤਾ ਗਿਆ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਜਿਸ ਦੀ  
ਜਾਰੀ ਕਰਨ ਦੀ ਮਿਤੀ 13.05.2024 ਹੈ, ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਉਕਤ ਫਾਇਰ ਸੇਫਟੀ  
ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ 31.03.2027 ਤੱਕ ਵਧਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਨਿੱਜੀ ਹੋਵੇਗੀ ਅਤੇ ਮਿਆਦ  
ਵਧਾਉਣ ਉਪਰੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਦਫਤਰ ਵੱਲੋਂ  
ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 12.05.2025 ਤੋਂ ਬਾਅਦ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।  
ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ  
ਤੇ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਤੇ ਤੇ  
ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ. 9979 ਮਿਤੀ 18-03-2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ  
ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।



ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ  
ਤੇ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

## Building Safety Report

Name of School:- Holy Heart Sr. Sec. Convent School (Sangrur)

I have visited the above-mentioned school Building along with Sh. Rishav Dev, Junior Engineer and on his visually inspection, it seems visually safe subject to the following observations and conditions:-

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building as per Drawings is 27594 Sq.ft
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **Two Year, upto 31/03/2027**, *subject to renewal of Fire Safety Certificate.*
- j) This Building Safety Certificate should not be considered as NOC for Road Access which will be taken separately by the School as per Government Policy No. 5/13/018-3BR3/1294287/3 Dated: 10.08.2018.

  
Sub Divisional Engineer  
Provincial Sub Division  
PWD B&R, Sangrur. 

(Provincial)

Serial No. Y

675556

28-3-2025

Received from

ਪ੍ਰਿੰਸੀਪਲ ਡੀ ਰਾਹਤ ਜੀਰੀਆ ਡੈਵਲਪਮੈਂਟ  
ਏਂਡ ਮਨੁੱਖ ਸੰਗਰੂਰ

with letter No

dated

20

the sum of Rupees

20000/-

in Cash/by Cheque on account of

ਮੰਡੀਆ ਚਾਰਜ

ਡੀ ਆਰ ਡਿਵੀਜ਼ਨ ਡੈਵਲਪਮੈਂਟ

in

payment of

Rs

Signature

Sub Divisional Engineers

Provincial Sub Division

Designation

PWD B&R SANGRUR